

### TEST REPORT

Report No.: HC90065/2014 Page: 1 of 4 September 16, 2014 Date:

NEOUSYS TECHNOLOGY INC. 15F, NO. 868-3, ZHONGZHENG RD., ZHONGHE DIST., NEW TAIPEI CITY, TAIWAN

The following merchandise was submitted and identified by the vendor as: Product Description: **Fanless Controller** Style/ Item No.: Nuvo-3100VTC(with 2.5 Inch SSD)/No.1 **Quantity:** Total 1 piece Sep. 16, 2014 Testing Period:

We have tested the submitted sample(s) as requested and the following results were obtained: Test Required: (According to client's test specification, please see following sheets in detail.) 1. Random Vibration Test

Test Results: - PLEASE SEE ATTACHED SHEETS -

> Signed for and on behalf of SGS TAIWAN Ltd.

Hank Chiou Asst. Supervisor

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction unadviful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司

No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號 t (886-2) 2299-3279 f (886-2) 2299-9558

www.tw.sas.com Member of SGS Group

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號



# TEST REPORT

Report No.:	HC90065/2014		
Page:	2	of	4

#### 1. Random Vibration Test

Test	Eq	ui	pn	nei	nt:

Brand	Model	Serial No.
King Design	EM-800F2K-50N120	RU104080389
Dactron	COMET 200	10539718
PCB	353B34	139174
	King Design Dactron	King DesignEM-800F2K-50N120DactronCOMET 200

### Lab Environmental Conditions:

Ambient temperature:	<u>(25 ± 3) °C</u>
Ambient humidity:	<u>(55 ± 20) % RH</u>

#### Test Method/ Specification:

Test method:	Reference to IEC 60068-2-64, Edition 2.0: 2008			
Sample condition:	Operating (pow	er on)		
Wave form:	Random			
Frequency:	<u>(5 ~ 500) Hz</u>			
	Frequency (Hz)	Left Slope (dB/Oct.)	PSD (G <sup>2</sup> /Hz)	Right Slope (dB/Oct.)
	5	-	0.051	0
	500	0	0.051	—
	$\implies$ equivalent to 5.0 G <sub>rms</sub>			
Direction:	X, Y, Z axes (se	e photo 3 ~ 5)		
Duration:	30 minutes/ axis	<u>S</u>		

- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then examine the booting function could work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

 SGS Taiwan Ltd.
 No.134, Wu Kung Road, N

 台灣檢驗科技股份有限公司\_\_\_t (886-2) 2299-3279

f (886-2) 2299-9558

www.tw.sgs.com Member of SGS Group



## TEST REPORT

Report No.:	HC90065/2014		
Page:	3	of	4

Specimen:

Style/Item No.: Quantity:

Nuvo-3100VTC(with 2.5 Inch SSD)/ No.1 Total 1 piece

Test Result:

Check Item		
Style/ Item No.	Appearance check (Visual check)	Functional check
Nuvo-3100VTC(with 2.5 Inch SSD)/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.35, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司\_

t (886-2) 2299-3279 f (886-2) 2299-9558


www.tw.sgs.com Member of SGS Group



### TEST REPORT

Report No.:	HC90065/2014		
Page:	4	of	4

Test Photos:



### - — The End of Test Report — —

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司\_

t (886-2) 2299-3279 f (886-2) 2299-9558

www.tw.sgs.com Member of SGS Group