

## **Interfaces and Connectors**

	9					
	5 Gigabit Ethernet		Transfer F	Rate	5.000 Mbits/sec	
	2.5 Gigabit Ethernet Gigabit Ethernet Fast Ethernet Connector: M12 / 8-		Transfer F	Rate	2.500 Mbits/sec	
			Transfer F	Rate	1.000 Mbits/sec	
			Transfer F	Rate	100 Mbits/sec	
			pol x-coded			
		(SACC-CI-M12FS-8CON-L180-10G)				
	Assignment:	1 - MX1+			2 - MX1-	
		3 - MX2+			4 - MX2-	
		5 - MX4-	+		6 - MX4-	
		7 - MX3-	-		8 - MX3+	
Process Interface	Connector:	M12/12-pin a-coded				
		(SACC-CI-M12MS-12CON-L180)				
	Assignment:	1 - Powe	er Vcc		2 - GND (Power)	
		3 - IN1 (Line0)			4 - OUT1 (Line4)	
		5 - IN2 (Line1)			6 - OUT2 (Line5)	
		7 - OUT	3 (Line6)		8 - RS232 TxD	
		9 - OUT	4 (Line7)		(Line2)	

11 - GND (IO)

10 - RS232 RxD (Line3) 12 - Power (IO)


Data and Power Interface 10 Gigabit Ethernet Transfer Rate 10.000 Mbits/sec

Lens Control Interface NA (located within support, reserved for future use)

## **Optical Data**

Lens Mount	M58-Mount
Optical Filter	IR cut filter

## **Mechanical Data**



## **Environmental Data**